



3635 W Broadway • MISSOULA, MT 59806

**TECHNICAL BULLETIN
052813**

TITLE: RADIO PRE-WIRE CABLE PROTECTION BEFORE RADIO INSTALLATION

This bulletin is in response to a possible safety hazard found in Wildcat 643U Models manufactured between January 2010 and May 2013. This hazard is only found when a radio is not installed.

Recommended Corrective Action:

If a radio is not installed, or has been removed, use high quality electrical tape to cover the end of the Mini-UHF Coaxial radio pre-wire cable to prevent contact with the positive terminal found in the Console of the apparatus. Contact with this terminal could cause a short and a possible fire. A picture of this condition before and after corrective action is included in this bulletin.

If a radio is installed, no action is required.

All Apparatus manufactured after May 28, 2013 will have a protective liquid insulation coating or rubber boot applied to the positive terminal found in the Console of the apparatus to prevent contact with the coaxial radio pre-wire.



Before



After

If you need further information, contact us by phone at: (406) 728-5070, or via e-mail: aidenc@wildcatfiretrucks.com.

***There's Nothing Tougher Than A Wildcat.
Phone: (406) 728-5070 Fax: (406) 721-9668***