



5.10 Waterbreaks

A waterbreak is a system of woody buffers located to manage flooding and encourage sediment deposition. A primary waterbreak is orientated parallel to the river and secondary waterbreaks perpendicular to flood flows. Woody buffers next to levees on the channel side can protect levees from breaching and can reduce damage to levees when they do breach.

5.10 References

Allen, S.B.; Dwyer, J.P.; Wallace, D.C.; Cook, E.A. 2003. Missouri River flood of 1993: role of woody corridor width in levee protection. *Journal of American Water Resources Association*. 39: 923-933.

Dwyer, J.P.; Wallace, D.C.; Larsen, D.R. 1997. Value of woody river corridors in levee protection along the Missouri River in 1993. *Journal of the American Water Resources Association*. 33: 481-489.

Geyer, W.A.; Nepl, T.; Brooks, K.; Carlisle, J. 2000. Woody vegetation protects streambank stability during the 1993 flood in central Kansas. *Journal of Soil and Water Conservation*. 55: 483-486.

Shields, F.D.; Gray, D.H. 1992. Effects of woody vegetation on sandy levee integrity. *Water Resources Bulletin*. 28: 917-931.

Wallace, D.C.; Geyer, W.A.; Dwyer, J.P. 2000. Waterbreaks: managed trees for floodplains. *Agroforestry Notes* 19. Lincoln, NE: USDA National Agroforestry Center. 4 p. <http://www.unl.edu/nac/agroforestrynotes/an19sa04.pdf>. [Date accessed: September 26, 2007].